

# UG热键一览表

热键		Application	对应菜单	功能
	<b>F1</b>		Help -> Context...	
	<b>F2</b>			
	<b>F3</b>		View -> Current Dialog	
	<b>F4</b>		View -> Information	
	<b>F5</b>		View -> Refresh	
	<b>F6</b>			
	<b>F7</b>			
	<b>F8</b>			
	<b>F9</b>			
	<b>F10</b>			
	<b>F11</b>			
	<b>F12</b>			
Ctrl-	<b>A</b>		View -> Assembly Navigator	
Ctrl-Shift-	<b>A</b>		File -> Save As...	
Ctrl-Alt-	<b>A</b>			
Ctrl-	<b>B</b>		Edit -> Blank -> Blank...	
Ctrl-Shift-	<b>B</b>		Edit -> Blank -> Reverse Blank All	
Ctrl-Alt-	<b>B</b>	Manufacturing	Tools -> Boundary...	
Ctrl-	<b>C</b>		Edit -> Copy	
Ctrl-Shift-	<b>C</b>		View -> Curature Graphs	
Ctrl-Alt-	<b>C</b>		Tools -> CLSF...	
Ctrl-	<b>D</b>		Edit -> Delete...	
Ctrl-Shift-	<b>D</b>			
Ctrl-Alt-	<b>D</b>			

# UG热键一览表

Ctrl-	<b>E</b>		Tools -> Expression...	
Ctrl-Shift-	<b>E</b>			
Ctrl-Alt-	<b>E</b>			
Ctrl-	<b>F</b>		View -> Operation -> Fit	
Ctrl-Shift-	<b>F</b>		Format -> Layout -> Fit All Views	
Ctrl-Alt-	<b>F</b>			
Ctrl-	<b>G</b>		File -> Execute UG/Open -> Grip...	
Ctrl-Shift-	<b>G</b>		File -> Execute UG/Open -> Debug Grip...	
Ctrl-Alt-	<b>G</b>			
Ctrl-	<b>H</b>			
Ctrl-Shift-	<b>H</b>		View -> Visualization -> High Quatity Image	
Ctrl-Alt-	<b>H</b>			
Ctrl-	<b>I</b>		Information -> Object...	
Ctrl-Shift-	<b>I</b>			
Ctrl-Alt-	<b>I</b>			
Ctrl-	<b>J</b>		Edit -> Object Display...	
Ctrl-Shift-	<b>J</b>		Preferences -> Object...	
Ctrl-Alt-	<b>J</b>			
Ctrl-	<b>K</b>			
Ctrl-Shift-	<b>K</b>		Edit -> Blank -> Unblank Selected...	
Ctrl-Alt-	<b>K</b>			
Ctrl-	<b>L</b>		Format -> Layer Settings...	
Ctrl-Shift-	<b>L</b>			
Ctrl-Alt-	<b>L</b>			
Ctrl-	<b>M</b>		Application -> Modeling...	

# UG热键一览表

Ctrl-Shift-	<b>M</b>		View -> Model Navigator	
Ctrl-Alt-	<b>M</b>		Application -> Manufacturing...	
Ctrl-	<b>N</b>		File -> New...	
Ctrl-Shift-	<b>N</b>		Format -> Layout -> New...	
Ctrl-Alt-	<b>N</b>	Manufacturing	Tools -> Unisim...	
Ctrl-	<b>O</b>		File -> Open...	
Ctrl-Shift-	<b>O</b>		Format -> Open...	
Ctrl-Alt-	<b>O</b>			
Ctrl-	<b>P</b>		File -> Plot...	
Ctrl-Shift-	<b>P</b>		Tools -> Macro -> Playback...	
Ctrl-Alt-	<b>P</b>			
Ctrl-	<b>Q</b>			
Ctrl-Shift-	<b>Q</b>		View -> Visualization -> Create Quick Image	
Ctrl-Alt-	<b>Q</b>			
Ctrl-	<b>R</b>		View -> Operation -> Rotate...	
Ctrl-Shift-	<b>R</b>		Tools -> Macro -> Start Record...	
Ctrl-Alt-	<b>R</b>			
Ctrl-	<b>S</b>		File -> Save	
Ctrl-Shift-	<b>S</b>		Tools -> Macro -> Step...	
Ctrl-Alt-	<b>S</b>			
Ctrl-	<b>T</b>		Edit -> Transform...	
Ctrl-Shift-	<b>T</b>		Preferences -> Selection...	
Ctrl-Alt-	<b>T</b>			
Ctrl-	<b>U</b>		File -> Execute UG/Open -> User Function...	
Ctrl-Shift-	<b>U</b>		Edit -> Blank -> Unblank All of Part	

# UG热键一览表

Ctrl-Alt-	<b>U</b>			
Ctrl-	<b>V</b>		Edit -> Paste	
Ctrl-Shift-	<b>V</b>		Format -> Visible in View...	
Ctrl-Alt-	<b>V</b>			
Ctrl-	<b>W</b>		Application -> Gateway	
Ctrl-Shift-	<b>W</b>			
Ctrl-Alt-	<b>W</b>		Application -> Assemblies	
Ctrl-	<b>X</b>		Edit -> Cut	
Ctrl-Shift-	<b>X</b>			
Ctrl-Alt-	<b>X</b>	Manufacturing	Tools -> Lathe Cross-Section...	
Ctrl-	<b>Y</b>			
Ctrl-Shift-	<b>Y</b>			
Ctrl-Alt-	<b>Y</b>			
Ctrl-	<b>Z</b>		Edit -> Undo List	
Ctrl-Shift-	<b>Z</b>		View -> Operation -> Zoom...	
Ctrl-Alt-	<b>Z</b>			